

```

07:42:00      CLR Call Monitor: Call RSSI value
4113      Source: 6      CCP0
                        (407)3250010 cell 201 frssi -81 rrssi -83 attn 2
fber 0 rber 0      Object: 20      A      TC 780
                        Class: XXXXXXXXXXXXXXXX
Domain:2      BTS:1 Chassis:      Slot:0      Port:
007:42:00      CLR Call Monitor: Adjacent cell RSSI values from mobile
4116      Source: 6      CAP2
                        (407)3250010 Cell_id/RSSI: 32/-97 202/-113 491/-103
Object: 6      CAP2
                        Class: XXXXXXXXXXXXXXXX
Domain:2      Chassis:6      Slot:11      Port:
07:42:00      CLR Call Monitor: Adjacent cell RSSI values from mobile
4116      Source: 6      CAP2
                        (407)3250010 Cell_id/RSSI: 412/-87 323/-109 203/-103
Object: 6      CAP2
                        Class: XXXXXXXXXXXXXXXX
Domain:2      Chassis:6      Slot:11      Port:
007:42:00      CLR Call Monitor: Adjacent cell RSSI values from mobile
4116      Source: 6      CAP2
                        (407)3250010 Cell id / RSSI: 1353/-113
Object: 6      CAP2
                        Class: XXXXXXXXXXXXXXXX
Domain:2      Chassis:6      Slot:11      Port:
07:42:01      CLR Call Monitor: Call RSSI value
4113      Source: 6      CCP0
                        (407)3250010 cell 201 frssi -81 rrssi -84 attn 2
fber 0 rber 0      Object: 20      A      TC 780
                        Class: XXXXXXXXXXXXXXXX
Domain:2      BTS:1 Chassis:      Slot:0      Port:
007:42:01      CLR Call Monitor: Call Handoff has taken place
4104      Source: 2      CCP0
                        Ph#:(407)3250010 Handoff from 201 to 32
Object: 3      B      TC 755
                        Class: XXXXXXXXXXXXXXXX
Domain:1      BTS:2 Chassis:      Slot:0      Port:
07:42:01      CLR Call Monitor: Call Path Assigned
4101      Source: 2      CCP0
                        Ph#:(407)3250010 Handin connect E1: 0, 7 T1: 0, 4
755 TDMA-3      Object: 3      B      TC 755
                        Class: XXXXXXXXXXXXXXXX
Domain:1      BTS:2 Chassis:      Slot:0      Port:
007:42:01      CLR Call Monitor: Adjacent cell RSSI values from mobile
4116      Source: 6      CAP2
                        (407)3250010 Cell_id/RSSI: 32/-97 202/-113 491/-101
Object: 6      CAP2
                        Class: XXXXXXXXXXXXXXXX
Domain:2      Chassis:6      Slot:11      Port:

```

Figure 1







Figure 2

STANDARD FILE FORMAT

Subscriber Number
Serving cell site
Channel
Channel type
Mobile power
F_RSSI₁, F_RSSI₂, ..., F_RSSI_n
R_RSSI₁, R_RSSI₂, ..., R_RSSI_n
F_BER₁, F_BER₂, ..., F_BER_n
R_BER₁, R_BER₂, ..., R_BER_n
Call_event₁, Call_event₂, ..., Call_event_n
NEIGHBOR_RSSI₁, NEIGHBOR_RSSI₂, ..., NEIGHBOR_RSSI_n
TimeStamp₁, Lat/Long₁, ..., TimeStamp_n, Lat/Long_n
:
:
:

Figure 3





Sub Number **261** Serving Cell Channel **262** R-Rssi **263** R-Ber **264** F-Rssi **265** F-Ber **266** ChanType MSPOW **267**

8133612002 T0058 MDVC-320 T018A T004A T005A T004B T018C T005C T017A T017A T017A

-93 -97 -105 -105 -107 -111 -113 -113 -112 -113

270 270 270 270 270 270 270 270 270 270

290 → Sound On

Figure 4B






Fig. 5



00320" 56702969




Figure 7